

OVERVIEW SUMMARY REPORT

Specialist Fire Door Inspections and Consultancy Services
Company no. 15471358

London Fire Door Consultants Ltd

FDIS CERTIFIED FIRE DOOR INSPECTION OF EXISTING DOORS

5th Floor
167-169 Great Portland Street
W1W 5PF

www.londonfiredoorconsultants.co.uk
07745 895191



On Site Inspection Project
On Site Inspection Name of Responsible Person/Landlord
On Site Inspection Additional Duty Holder/Managing Agent
On Site Inspection Person(s) Consulted during Inspection
On Site Inspection Date of Inspection

Refer to LFDC FDIS Certified Inspection DETAILED CHECKLIST for full details of recommended remedial work for 3rd party certified fire door maintenance contractor to carry out.

SEQ	TYPE OF DOOR ASSEMBLY	FRAME	DOOR	SEALS	GLAZING	CLOSER	HINGES	PIVOTS	LOCKS/LATCH	ELECTRIC ACCESS CONTROL	OPENING FURNITURE	INT. MATERIAL	SHIMMING	SPRING EXTENSION	STATUS																	
1	5th NW Lift Lobby	YES F0365	YES ULSADD	NOT KNOWN	*10mm-10.5mm	N/A	NOT KNOWN	YES	YES	NO	NOT KNOWN	-	-	-	Powered	YES	YES	-	-	-	YES	YES	NO	NO	YES	YES	NON-CERTIFIED	NON-COMPLIANT	NORMAL	LH X3241006 + RH X3241007		
2	5th NE Lift Lobby	YES F0365	YES ULSADD	NOT KNOWN	*10.5mm-10mm	N/A	NOT KNOWN	YES	YES	NO	NOT KNOWN	-	-	-	Powered	NO	YES	YES	YES	YES	NO	NOT KNOWN	-	-	-	YES	YES	NON-CERTIFIED	NON-COMPLIANT	NORMAL	LH X3241008 + RH X3241009	
3	5th NE FT Lobby	YES F0365	YES ULSADD	YES	YES	NO	YES	YES	YES	YES	YES	YES	YES	YES	Powered	YES	YES	YES	YES	YES	NO	NOT KNOWN	-	-	-	NO	YES	YES	NON-CERTIFIED	NON-COMPLIANT	NORMAL	X3241009
4	5th North FT Lobby/Store	YES F0365	YES ULSADD	YES	YES	NO	NO	YES	YES	YES	YES	YES	YES	YES	Powered	YES	YES	YES	YES	YES	NO	NOT KNOWN	-	-	-	NO	YES	YES	NON-CERTIFIED	NON-COMPLIANT	NORMAL	X3241011
5	5th South FT Lobby/Entrance	YES F0365	YES ULSADD	YES	YES	NO	NO	YES	YES	YES	YES	YES	YES	YES	Powered	YES	NOT KNOWN	YES	YES	YES	NO	NOT KNOWN	-	-	-	NO	YES	YES	NON-CERTIFIED	NON-COMPLIANT	NORMAL	X3241012
6	5th South FT Lobby/Store	YES F0365	NO ULSADD	YES	YES	NO	NO	YES	YES	YES	YES	YES	YES	YES	Powered	YES	YES	YES	YES	YES	NO	NOT KNOWN	-	-	-	NO	YES	YES	NON-CERTIFIED	NON-COMPLIANT	NORMAL	X3241013
7	5th Ladies WC	YES F0365	YES ULSADD	YES	YES	NO	NO	YES	YES	YES	YES	YES	YES	YES	Powered	YES	YES	YES	YES	YES	NO	NOT KNOWN	-	-	-	NO	YES	YES	NON-CERTIFIED	NON-COMPLIANT	NORMAL	X3241014
8	5th Single WC	YES F0365	YES ULSADD	YES	YES	NO	NO	YES	YES	YES	YES	YES	YES	YES	Powered	YES	YES	YES	YES	YES	NO	NOT KNOWN	-	-	-	NO	YES	YES	NON-CERTIFIED	NON-COMPLIANT	NORMAL	X3241015
9	5th Male WC	YES F0365	YES ULSADD	YES	YES	NO	NO	YES	YES	YES	YES	YES	YES	YES	Powered	YES	YES	YES	YES	YES	NO	NOT KNOWN	-	-	-	NO	YES	YES	NON-CERTIFIED	NON-COMPLIANT	NORMAL	X3241016
10	5th Ambulant WC Riser	YES F0365	YES ULSADD	YES	YES	NO	NO	YES	YES	YES	YES	YES	YES	YES	Powered	YES	YES	YES	YES	YES	NO	NOT KNOWN	-	-	-	NO	YES	YES	NON-CERTIFIED	NON-COMPLIANT	NORMAL	X3241017
11	5th South Conc. Riser	YES F0365	YES ULSADD	NO	*10mm-10.5mm	YES	NO	YES	YES	YES	YES	YES	YES	YES	Powered	YES	YES	YES	YES	YES	NO	NOT KNOWN	-	-	-	NO	YES	YES	NON-CERTIFIED	NON-COMPLIANT	NORMAL	X3241018
12	5th North West Conc. Riser	YES F0365	YES ULSADD	NO	*11.5mm-12mm	NO	NO	YES	YES	YES	YES	YES	YES	YES	Powered	NO	NOT KNOWN	-	-	-	NO	NOT KNOWN	-	-	-	NO	YES	YES	NON-CERTIFIED	NON-COMPLIANT	NORMAL	X3241019
13	5th South Conc. LH Riser	YES F0365	YES ULSADD	NO	*10mm-12.5mm	NO	NO	YES	YES	YES	YES	YES	YES	YES	Powered	YES	YES	YES	YES	YES	NO	NOT KNOWN	-	-	-	NO	YES	YES	NON-CERTIFIED	NON-COMPLIANT	NORMAL	LH X3241106 + RH X3241101
14	5th South West Conc. RH Riser	YES F0365	YES ULSADD	NO	*10mm-12.5mm	NO	NO	YES	YES	YES	YES	YES	YES	YES	Powered	YES	YES	YES	YES	YES	NO	NOT KNOWN	-	-	-	NO	YES	YES	NON-CERTIFIED	NON-COMPLIANT	NORMAL	LH X3241105 + RH X3241104
15	5th South West Conc. Centre Riser	YES F0365	YES ULSADD	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES	Powered	YES	YES	YES	YES	YES	NO	NOT KNOWN	-	-	-	NO	YES	YES	NON-CERTIFIED	NON-COMPLIANT	NORMAL	LH X3241106 + RH X3241106
16	5th South West Conc. LH Riser	YES F0365	YES ULSADD	NO	*10mm-12.5mm	YES	NO	YES	YES	YES	YES	YES	YES	YES	Powered	YES	YES	YES	YES	YES	NO	NOT KNOWN	-	-	-	NO	YES	YES	NON-CERTIFIED	NON-COMPLIANT	NORMAL	LH X3241107 + RH X3241108
17	5th North West Conc. RH Riser	YES F0365	YES ULSADD	NO	*10mm-14.5mm	NO	NO	YES	YES	YES	YES	YES	YES	YES	Powered	YES	YES	YES	YES	YES	NO	NOT KNOWN	-	-	-	NO	YES	YES	NON-CERTIFIED	NON-COMPLIANT	NORMAL	X3241110
18	5th North West Conc. LH Riser	YES F0365	YES ULSADD	NO	*10mm-12.5mm	YES	NO	YES	YES	YES	YES	YES	YES	YES	Powered	YES	YES	YES	YES	YES	NO	NOT KNOWN	-	-	-	NO	YES	YES	NON-CERTIFIED	NON-COMPLIANT	NORMAL	LH X3241110 + RH X3241111
19	5th North East Conc. RH Riser	YES F0365	YES ULSADD	NO	*10mm-12.5mm	NO	NO	YES	YES	YES	YES	YES	YES	YES	Powered	YES	YES	YES	YES	YES	NO	NOT KNOWN	-	-	-	NO	YES	YES	NON-CERTIFIED	NON-COMPLIANT	NORMAL	LH X3241112 + RH X3241113
20	5th North East Conc. Centre Riser	YES F0365	YES ULSADD	NO	*10mm-14.5mm	YES	YES	YES	YES	YES	YES	YES	YES	YES	Powered	YES	YES	YES	YES	YES	NO	NOT KNOWN	-	-	-	NO	YES	YES	NON-CERTIFIED	NON-COMPLIANT	NORMAL	LH X3241114 + RH X3241115
21	5th North East Conc. LH Riser	YES F0365	YES ULSADD	NO	*10mm-12.5mm	YES	NO	YES	YES	YES	YES	YES	YES	YES	Powered	YES	YES	YES	YES	YES	NO	NOT KNOWN	-	-	-	NO	YES	YES	NON-CERTIFIED	NON-COMPLIANT	NORMAL	LH X3241116 + RH X3241117
22	5th South East Conc. RH Riser	YES F0365	YES ULSADD	NO	*10mm-12.5mm	NO	NO	YES	YES	YES	YES	YES	YES	YES	Powered	YES	YES	YES	YES	YES	NO	NOT KNOWN	-	-	-	NO	YES	YES	NON-CERTIFIED	NON-COMPLIANT	NORMAL	LH X3241118 + RH X3241119
23	5th South East Conc. LH Riser	YES F0365	YES ULSADD	NO	*10mm-12.5mm	NO	NO	YES	YES	YES	YES	YES	YES	YES	Powered	YES	YES	YES	YES	YES	NO	NOT KNOWN	-	-	-	NO	YES	YES	NON-CERTIFIED	NON-COMPLIANT	NORMAL	LH X3241120 + RH X3241121



Compliant with BS 8214:2016?



